An aerial photograph of a power substation. In the foreground, there is a complex arrangement of high-voltage electrical equipment, including busbars, insulators, and transformers, all supported by metal structures. A paved walkway or road runs through the middle of the station. In the background, there are several large, light-colored buildings, likely control or maintenance buildings, and a parking lot filled with cars. The surrounding area is a mix of open land and some trees, with hills visible in the far distance under a clear sky.

**Operating Experience
Overview and
SF₆ Emission
Reduction Efforts at
Seabrook Station**

Seabrook Station

345-kV Distribution System

- **7 independent bus duct zones containing approximately 28,000 lbs. of SF₆ gas.**
- **8 power circuit breakers containing 1,770 lbs. of SF₆ gas (14,160 lbs. total).**
- **Initially placed into service in 1982 to supply off-site power during construction of Seabrook Station.**
- **Commenced commercial operation in 1990.**

345-kV Distribution System Design

SF₆ Bus Duct Design

- **Original ITE design bus duct included:**
 - 6-inch hollow aluminum pipe for the conductor.
 - 18-inch outer aluminum enclosure.
 - Insulators composed of a cyclo-aliphatic epoxy with an alumina filler (1,037 total).
 - 9 porcelain air bushings at the transmission line interface.

SF₆ Power Circuit Breaker Design


- **ITE design power circuit breakers:**
 - The low pressure (LP) subsystem, 40 to 45 psig, provides insulation.
 - The high pressure (HP) subsystem, 265 psig nominally, provides SF₆ for arc extinguishing.






SF₆ Bus Duct Failures (1982-1989)

- **Insulator failures (8 total) attributed to:**
 - **Aluminum particle contamination, resulting in partial discharges and SF₆ breakdown (1 failure).**
 - **Loss of spring contact at the conductor surface resulting in a floating component (4 failures).**
 - **Voids between epoxy coating and the aluminum insert (2 failures).**
 - **Indeterminate (1 failure).**
- **Air bushing failures (2 total) attributed to:**
 - **Excessive mechanical loading from cable contraction during cold conditions.**
 - **Excessive mechanical loading from cable sway during wind conditions.**



SF6 INSULATOR
WITH CENTER CONDUCTOR







Consequences of SF₆ Bus Duct Failures

- **Zones 3, 6, and 7 – connect switchyard to 3 sets of overhead transmission lines. Loss of a single bus duct due to insulator failure required 8 days for repair at manufacturer’s facility. Unit operation can continue with two sources of off-site power.**
- **Zone 2 – connects switchyard to reserve auxiliary transformers. Loss of capability to supply off-site power from two independent sources. Requires unit shutdown unless restored within 24 hours.**
- **Zone 4 – connects generator step up transformers to switchyard. Loss of electrical load requiring immediate reactor shutdown.**
- **Air bushing failures – loss of SF₆ gas inventory for affected zone (Zones 3, 6, or 7).**

1012148




FIG. 1 CONICAL INSULATOR FIRED GAS PASS WITH PLUG CONTACT




FIG. 2 CONICAL INSULATOR FIRED GAS PASS OR GAS BARRIER WITH SOCKET CONTACT

QTY	SYMBOL	QTY	SYMBOL	QTY	SYMBOL	QTY	SYMBOL
1	163	23	21	23	222	230	230
2	230	43	182	113	242	1028	573
3	213	23	177	142	242	230	230
4	430	23	177	142	242	230	230
5	530	23	177	142	242	230	230
6	630	23	177	142	242	230	230
7	730	23	177	142	242	230	230
8	830	23	177	142	242	230	230
9	930	23	177	142	242	230	230




FIG. 3 CONICAL INSULATOR FIRED ELBOW OTHERWISE SAME AS FIGURE 1 CONICAL INSULATOR FIG. 1

REV	DATE	BY	CHKD	APP
1	10/12/48			

THE INSULATOR
 THE CONICAL OUTLINE

APP

1012148

Corrective Actions


- **Bus duct modifications, Zones 2 and 4 – replace with new Westinghouse/ABB design.**
 - Implemented in 1992 for Zone 2.
 - Implemented in 1997 for Zone 4.
 - Cost: \$1.9 million.
- **Porcelain air bushing replacement with epoxy composite bushings.**
 - Replacement implemented in 1993, but not before two additional failures occurred in 1991 and 1992.
 - Cost: \$900,000 for 9 composite bushings.
- **Establish an on-site facility for repair of SF₆ bus duct sections and power circuit breakers.**
 - Implemented in 1992.
 - Cost: \$430,000.

Performance Since Implementation of Corrective Actions

- **No insulator failures experienced in Zones 2 or 4.**
- **Insulator failures continue at a rate of one per year in other zones.**
- **No air bushing failures since installation of composite bushings.**
- **On-site test and repair capability has reduced repair time from 8 days to 5 days on average.**


Present Leakage Reduction Measures

- **October 1999 EPRI Gas-Vue Leak Detection System survey of SF₆ bus ducts and power circuit breakers.**
- **Identified leakage areas have been reviewed and repair activities have been incorporated into the station maintenance schedule for 2000-2002.**
- **Follow-up survey planned following completion of repair activities.**














REMOVAL OF THIS COVER WILL
RESULT IN EQUIPMENT DAMAGE.



