U.S. Environmental Protection Agency Region 9 Oil Program

SPCC PHOTOGRAPHIC LOG

Facility Name & Location:

ALLENCO ENERGY LOS ANGELES CA

Photographer: WITUL

Camera: CANON SX230

Dates Photographs Were Taken:

11/6/2013

Photo No. Time: 1 045*

Direction Photo Taken:

Ν

Photo Description:

EXTERIOR OF WATER INJECTION PUMP HOUSE. TRENCH SUMP UNDER GRATING.

NOTE: CAMERA NOT SET FOR PST



Photo No.

Time: 1047

Direction Photo Taken:

ENE

Photo Description:

PORTABLE CONTAINERS OF INHIBITORS (e.g. CORROSION) IN SECONDARY CONTAINMENT



Photo No. Time: 1048

Direction Photo Taken:

Ν

Photo Description:

ADDITIONAL VIEW OF INHIBITOR CONTAINERS IN SECONDARY CONTAINMENT



Photo No.

Time: 1049

Direction Photo Taken:

Ε

Photo Description:

VIEW ABOVE WELL GALLERY



Photo No. 5 Time: 1050

Direction Photo Taken:

Е

Photo Description:

AREA ABOVE WELL GALLERY



Photo No. 6 Time: 1051

Direction Photo Taken:

S

Photo Description:

HYDRAULIC OIL TANKS IN SECONDRY CONTAINMENT – TANK AT RIGHT IN USE



Photo No. Time: 7 1052

Direction Photo Taken:

W

Photo Description:

AREAS OF DISCOLORATION, POSSIBLY WEEPING FROM HISTORICAL EVENT, OR SEEPAGE FROM BEYOND WALL. HYDRAULIC OIL TANKS AT RIGHT OF IMAGE.



Photo No.

Time: 1053

Direction Photo Taken: WNW

Photo Description:

SOME AREAS OF DISCOLORATION ON PAVED AREA.



Photo No. Time: 9 1054

Direction Photo Taken:

NE NE

Photo Description:

WELL GALLERY EAST ENTRANCE AND TRANSFER PIPES AT RIGHT.



Photo No. 10 Time: 1100

Direction Photo Taken: WNW

Photo Description:

WELL GALLERY EAST ENTRANCE WITH H2S WARNING SIGN IN PLACE ON RAIL.



Photo No. 11 1101

Direction Photo

Taken:

Photo Description:

WELL PIPING AND TRENCH IN GALLERY



Photo No. 12 Time: 1102

Direction Photo Taken:

۱۸/

Photo Description:

TRENCH PUMP IN WELL GALLERY TRENCH



Photo No. 13 Time: 1104

Direction Photo Taken:

Photo Description:

TRENCH PUMP IN WELL GALLERY TRENCH



Photo No. 14 Time: 1105

Direction Photo Taken:

S

Photo Description:

TRENCH PUMP IN WELL GALLERY TRENCH



Photo No. 15 Time: 1106

Direction Photo Taken:

Photo Description:

PIPING SUPPORTS IN WELL GALLERY



Photo No. 16 Time: 1107

Direction Photo Taken:S

Photo Description:

LUMBER USED AS PIPING SUPPORT IN WELL GALLERY



Photo No. 17 1115

Direction Photo Taken:

Photo Description:

LUMBER USED AS PIPING SUPPORTS FOR WELL #19 TEST LINES (CURRENTLY IDLE)



 Photo No.
 Time:

 18
 1115

Direction Photo Taken:

Photo Description:

TEST LINES (AT LEFT) TO WELL #19 (IDLE) AND #19 WELL HEAD AT RIGHT



Photo No. 19 1120

Direction Photo Taken:

E

Photo Description:

PHOTO OF TANK FARM CONTAINMENT AREA; VIEW INCLUDES LOCATION WHERE H2S DANGER SIGN HAD PREVIOUSLY BEEN ON RAILING



Photo No. 20 Time: 1121

Direction Photo Taken:

NE

Photo Description:

TANK FARM CONTAINMENT AREA, SCRUBBER AT LEFT (IN PIT).



Photo No. Time: 1125

Direction Photo Taken:

Е

Photo Description:

FREE WATER KNOCK OUT TANK – CAPACITY 500 BBLS (21,000 GAL) PER SPCC PLAN.



Photo No. 22 1128

Direction Photo Taken:

S

Photo Description:

TRAVIS CAIN, JEREMY JOHNSTONE AND SEPARATOR TANKS



Photo No. Time: 1128

Direction Photo Taken:

NE

Photo Description:

CRUDE OIL TANK 2 AND TANK 3, MARKED 250 BBLS EACH (10,500 GAL)



Photo No. 24 1129

Direction Photo Taken: NE

Photo Description:

CRUDE OIL TANK 1, MARKED 250 BBLS (10,500 GAL)




Photo No. 25 Time: 1130

Direction Photo Taken:

F

Photo Description:

BRINE WATER TANK #3 AT REAR, BRINE WATER TANK #2 AT RIGHT, EACH MARKED 250 BBLS



Photo No. 26 Time: 1132

Direction Photo Taken: NNE

Photo Description:

BRINE WATER TANK #2, MARKED OUT OF SERVICE (NO OOS DATE FOUND ON TANK)



Photo No. 27 1133

Direction Photo Taken:

Photo Description:

CHEMICAL TREATMENT AREA, INSIDE TANK FARM CONTAINMENT AREA. STANDS/SUPPORTS FOR TANKS NOT ALL PROPERLY ENGINEERED.



Photo No. 28 Time: 1136

Direction Photo Taken: SSE

Photo Description:

LUMBER USED FOR PIPING SUPPORTS AT FWKO TANK



Photo No. 29 1146

Direction Photo Taken:

W

Photo Description:

#10 OLD VENT TANK LABELED OUT OF SERVICE, MARKED WITH OOS DATE OF 4/25/13



Photo No. 30 Time: 1146

Direction Photo Taken:

Ν

Photo Description:

ORANGE-SCENTED SOLVENT TOTE IN TANK FARM CONTAINMENT AREA



Photo No. 31 Time: 1147

Direction Photo Taken: NW

Photo Description:

RAMP AT TANK FARM CONTAINMENT AREA; PIPING PROTECTED FROM VEHICLES BY METAL GUARDS



Photo No. 32 Time: 1149

Direction Photo Taken:

S

Photo Description:

VIEW OF PAVEMENT IN AREA SHOWING EXCESSIVELY DARK IN GOOGLE MAP IMAGE – SEE END OF PHOTOLOG



Photo No. 33 Time: 1155

Direction Photo Taken:

NE.

Photo Description:

PUMP IN WATER INJECTION PUMP HOUSE.



Photo No. 34 Time: 1156

Direction Photo Taken:

NE

Photo Description:

COMPRESSOR VESSELS IN WATER INJECTION PUMP HOUSE.



Photo No. Time: 1156

Direction Photo Taken:

NE

Photo Description:

VAPOR RECOVERY UNIT AT REAR, COMPRESSOR AT RIGHT, AND PIPING - IN WATER INJECTION PUMP HOUSE.



Photo No. 36 Time: 1201

Direction Photo Taken:

Ν

Photo Description:

MICROTURBINES FOR GAS EXTRACTED AT FACILITY.



Photo No. 37 1202

Direction Photo Taken:

S

Photo Description:

UTILITY OWNED/OPERATED EQUIPMENT – INDUSTRIAL STATION IS-1332



Photographer: UNKNOWN

Photo No. Time: N/A UNKWN

Direction Photo Taken:

45 DEGREE IMAGE, FROM ABOVE

Photo Description:

GOOGLE MAP IMAGE OF FACILITY (AND PARKING STRUCTURE AT LEFT) FROM UNKNOWN YEAR

