



Picture 1: Overview of Pago Socio STP facing plant from front.



Picture 2: Entry to Pago Socio. Gate was blocked by concrete block wall.



Picture 3: Influent channel.



Picture 4: Blower housing for aeration system. Blowers were not operating.



Picture 5: Channel under brush carries plant discharge to percolation field.



Picture 6: Water from a leaking potable water line was running in a shallow ditch into the plant. Ditch was bridged by the board in the middle right.



Picture 7: Leaking potable water line.



Picture 8: Gardening material stored on top of percolation field.





Picture 9: Planters on top of percolation field.