## CHAPTER TEN

## SAMPLING METHODS

Prior to employing the methods in this chapter, analysts are advised to consult the disclaimer statement at the front of this manual and the information in Chapter Two for guidance on the allowed flexibility in the choice of apparatus, reagents, and supplies. In addition, unless specified in a regulation, the use of SW-846 methods is not mandatory in response to Federal testing requirements. The information contained in each procedure is provided by EPA as guidance to be used by the analyst and the regulated community in making judgements necessary to meet the data quality objectives or needs for the intended use of the data.

The following methods are found in Chapter Ten:

Method 0010:	Modified Method 5 Sampling Train
	Appendix A: Preparation of XAD-2 Sorbent Resin
	Appendix B: Total Chromatographable Organic Material Analysis
Method 0011:	Sampling for Selected Aldehyde and Ketone Emissions from Stationary Sources
Method 0020:	Source Assessment Sampling System (SASS)
Method 0023A:	Sampling Method for Polychlorinated Dibenzo- <i>p</i> -Dioxins and Polychlorinated Dibenzofuran Emissions from Stationary Sources
Method 0030:	Volatile Organic Sampling Train
Method 0031:	Sampling Method for Volatile Organic Compounds (SMVOC)
Method 0040:	Sampling of Principal Organic Hazardous Constituents from
	Combustion Sources Using Tedlar® Bags
Method 0050:	Isokinetic HCI/CI <sub>2</sub> Emission Sampling Train
Method 0051:	Midget Impinger HCI/CI <sub>2</sub> Emission Sampling Train
Method 0060:	Determination of Metals in Stack Emissions
Method 0061:	Determination of Hexavalent Chromium Emissions from
	Stationary Sources
Method 0100:	Sampling for Formaldehyde and Other Carbonyl Compounds in Indoor Air
Method 25D:	Determination of the Volatile Organic Concentration of Waste Samples
Method 25E:	Determination of Vapor Phase Organic Concentration in Waste Samples
Method 207:	A Method for Measuring Isocyanates in Stationary Source Emissions