
Lindsay Light Streeterville Thorium Monitoring Area



- *Deed restriction required due to uninvestigated or known contamination areas.
- **All surface contamination removed. Multiple properties within area have been cleaned up.
- †Demolition monitoring required.
- ††Thorium and Asbestos contamination present.



et

3.360

