

Stan A. Huber Consultants, Inc.

Health Physics and Radiation Safety Services

200 North Cedar Road - New Lenox, Illinois 60451-1751 - (800) 383-0468 or (815) 485-6161 - FAX (815) 485-4433 - Email sahci@sahci.com - Home Page www.sahci.com

October 29, 2012

Daniel R. Rest, P.E. HBK Engineering, LLC. 921 W. Van Buren St., Suite 100 Chicago, IL 60607

RE: Thorium Monitoring at Grand Ave. & St. Clair St. on 10/24/12

Dear Mr. Rest:

Stan A. Huber Consultants, Inc (SAHCI) was hired by your firm to provide radiation monitoring during the drilling of one soil boring at Grand Ave. and St. Clair St. in Chicago, Illinois. The monitoring was performed on October 24, 2012.

Instrumentation

Surface gamma scans were performed by Joel Ahrweiler using a Ludlum Model 2221 Scaler / Ratemeter with attached 2"x2" Nal probe. The instrument was calibrated on November 8, 2011. The USEPA action level of 7.1 picocuries per gram (pCi/g) total thorium for this instrument is 19,110 counts per minute (cpm). The average background count rate for this location was found to be between 7,400 cpm and 9,500 cpm.

Soil Gamma Scans

Gamma surface scans were performed using the Ludlum Model 2221 Scaler / Ratemeter described above. Data was collected by surveying each split spoon soil sample as it was obtained from the boring. Any additional soil that was removed from the boring was also monitored.

The maximum gamma count rates for each split spoon are detailed on the attached Radiation Survey Form. The count rates for the boring ranged from 7,400 cpm to 8,000 cpm. No count rates were found at any time that exceeded the threshold limit of 19,110 cpm.

Additional Monitoring

Since no count rates were identified above the 7.1 pCi/gram threshold limit, no additional soil sampling, air monitoring, or personnel monitoring were performed.

You will need to forward a copy of this report to the City of Chicago Department of Public Health (Attn: Rahmatunsia Begum) with the CDOT Permit Number in the subject line. I will be providing a copy of this report to USEPA, as required.

Thank you for your assistance with this project. If you have any questions or need additional information please call me at (815) 485-6161.

Sincerely,

Stan A. Huber Consultants, Inc.

Glenn Huber, CHP President

2007	,	10.2	2	
Page _	/	of	~	



Radiation Survey Form

Date:/	0/24/12	Technician: _	Joel Ahrma	161
Inst Model:	Ludlum 2221	Serial No. : _	134542	
Probe Type:	1"x1" Nal /2"x2" Nal Shielded / Not Shielded) Lift Elevation:	Surtue -> -30	
Background <u>7.</u>	4 - 9.5 kcpm	Action Level:	/ 9, //o_cpm	
	ions in circles. Record higher			1
it grid intersections	s (it required). Shade areas of	elevated counts and record	шах срш.	N
			→ scale)
	164 E.G	rand Park	19 40+	1
	164 E. G Building			
				$-\dot{\bigcirc}$
				St Cla
				_
	Sideualk			$-\!\!\!\bigcirc$
		1		
			100 58-12-417-01	-0
			e attached court	
0.0		d Ave.		
	019,	d AVE.		

Soil Boring Log Stan A. Huber Consultants, Inc

Date:

10/24/2012

Instrument ID:

Ludlum 2221

Techncian:

Joel Ahrweiler

serial no. 134542

Boring ID

SB-12-417-001 9 (HBK Engineering)

(unshielded)

Depth	Max CPM
S to -2.5'	8,000
-3.5' to -4.5'	7,500
-6' to - 7.5'	7,700
-8.5' to -10'	7,500
-13' to -15'	7,600
-18.5' to -20'	7,400
-23.5' to -25'	7,500
-28' to -30'	7,400