



AECOM  
303 East Wacker Drive, Suite 900  
Chicago, Illinois 60601

312.938.0300 tel  
312.938.1109 fax

August 19, 2010

Mr. Narendra Prasad  
Integrus Business Support, LLC  
Environmental Services Department  
130 East Randolph, 22nd Floor  
Chicago, IL 60601

EPA Region 5 Records Ctr.



375794

**Subject: Radiological Survey of Right-of-Way Utility Excavation  
Permit No 764468813  
Permit Address: 222 North Columbus Drive  
AECOM Project No 60157647**

Dear Mr. Prasad:

Pursuant to conditions specified in the permit found in Attachment A issued by the City of Chicago, radiation monitoring was required to be performed at the above referenced site. AECOM provided the required radiation surveillance on July 28, 2010 for the excavation a single one foot by one foot excavation opening to install corrosion protection materials for the gas main in the vicinity of the permitted address.

Surveying was performed for the asphalt, concrete, and soil removal for the excavations required for the installation of corrosion protection equipment for the gas main. A one foot by one foot area was saw cut into the asphalt and concrete surface, exposing the structural backfill material located below approximately 52 feet east of the West Lot Line of North Columbus Drive and 100 feet south of the South Lot Line of South Water Street. Documentation of the excavation location provided by INTREN can be found in Attachment B. After asphalt and concrete were removed, the installation contractor, INTREN, utilized a soil vacuum truck to remove subsurface soils to expose the main due to the minimal area of excavation. AECOM proceeded to monitor the soils in increments of approximately 15-inches to a depth of approximately 3-feet, 5-inches. Please note that the depth to which the Ludlum Model 2221 survey meter used by AECOM is designed to detect gamma radiation counts above the threshold level is at 18 inch increments. Surveyed soils were retained to backfill into the excavation upon completion of the installation of the corrosion detection materials.


The monitoring revealed no indication of soils above the specified clean-up threshold established by the United States Environmental Protection Agency (USEPA) for the Streeterville area of Chicago. The USEPA threshold for Chicago's Streeterville area is 7.1 picocuries per gram (pCi/g total radium (Ra-226 + Ra-228). Gamma radiation count measurements for the project were made using Ludlum Model 2221 survey meter and an unshielded 2 x 2 Nal probe (Model 44-10) with a 20-foot long cord due to the depth of excavations. For the instrument used, the gamma count indicative of the 7.1 pCi/g threshold was 7,567 counts per minute (cpm) unshielded. The field gamma measurements within the excavation and the spoil materials generated during the excavation process did not exceed the respective threshold values previously stated and ranged from a minimum of 2,200 cpm to a maximum of 3,500 cpm. Thus, there was no indication of the presence of radiologically-impacted material and/or an exceedance of the USEPA cleanup threshold of 7.1 pCi/g total radium.

Finally, as part of the permit conditions, this letter has been forwarded to:

Chicago Department of Environment  
Attention: Ms. Rahmat Begum  
30 North LaSalle Street, 25<sup>th</sup> Floor  
Chicago, Illinois 60602

Please contact us with any questions you have regarding this letter or the reported results.

Regards,



Jaclyn C. Webb  
Staff Engineer



Steven C. Kornder, Ph.D.  
Senior Project Geochemist

cc: Rahmat Begum, Chicago Department of Environment  
Verneta Simon, USEPA

Attachment A Permit  
Attachment B Excavation Location

**Attachment A**  
**Permit**



CITY OF CHICAGO DEPARTMENT OF ENVIRONMENT
FORM NO. DOE.ROW.02

City of Chicago
Richard M. Daley, Mayor

Department of Environment

Sadbu A. Johnston
Commissioner

Twenty-fifth Floor
30 North LaSalle Street
Chicago, Illinois 60602-2575
(312) 744-7606 (Voice)
(312) 744-6451 (FAX)
(312) 744-3586 (TTY)
http://www.cityofchicago.org

Notice is hereby given that the site you have requested a permit for is recorded with the City of Chicago Department of Environment as potentially having environmental contamination on the site and adjacent right-of-way. This environmental contamination could present a threat to human health and safety in connection with work performed at the site, or in the adjacent right-of-way, if proper safeguards are not employed.

A file containing detailed information regarding the aforementioned environmental contamination is available for review at the Department of Environment at 30 N. LaSalle St., 25th Floor, Chicago, Illinois 60602 during normal business hours (8:30AM -4:30PM, Monday through Friday). Contact (312) 744-7606 for an appointment. This file must be reviewed and the remainder of this form completed before the permit can be issued if the ground is exposed or excavated. Please note that for some locations, additional health and safety procedures may be required by law.

Please complete the following:

I have reviewed and understand the documents, maintained by the Department of Environment, regarding environmental contamination of the site and adjacent right-of-way. Further, I will ensure that all work at the subject site and adjacent right-of-way, and any monitoring required including but not limited to radiation monitoring, will be performed in a manner that is protective of human health and the environment and in compliance with all applicable local, state, and federal laws, rules, and regulations, especially those pertaining to worker safety and waste management. I will ensure that the results of any radiation monitoring and/or surveying conducted shall be provided to the Department of Environment and the United States Environmental Protection Agency within two (2) weeks of their completion. If any elevated levels of radioactive material are detected, I will immediately contact the United States Environmental Protection Agency at (800) 424-8802.

Permit No.

7624468813

Date

6/4/10

Site Address

222 N. Columbus St

Work Location (Describe exact site location and attach map)

Street, sidewalk, driveway, curbside & tripole area

Nature of Work

Garage

Expected Start Date

ASAP

Applicant Name (print)

Harri O Oliver

Signature

Harri O Oliver

Date

6/4/10

Company

Peoples Gas

Company Address / Phone No.

130 E Randolph (312) 240-4692

Check if City Department Work

Department Name

General / Prime Contractor

Sal Balani

Include subcontractor information if applicable

Address

130 E Randolph

Phone No.

(773) 395-7446

Safety Officer / Phone No.

Joshua Walker (773) 542-7838

Radiation Contractor / Phone No. (if applicable)

Steve Konder AECOM (847) 279-2500

Department of Environment Approval / Date

Rahmatunisa Begum 6/4/10

Please return this completed form to the City of Chicago Department of Transportation at 30 N. LaSalle St., Room 1101, Chicago, Illinois 60602 during normal business hours (8:30 AM - 4:30 PM, Monday through Friday).

For DOE Use Only



**Attachment B**  
**Excavation Location**

# MAIN MAINTENANCE TICKET

ADDRESS

222 N. Lower Columbus Dr.

MAIN LOCATION				LOCATION FROM INTERSECTING STREET				INTERSECTING STREET		PROD. DIR.
FEET FROM LL	NSEW OF	NSEW LL	PROD. DIR.	FEET FROM LL	NSEW OF	NSEW LL	DIR.			
52	E	W		100	S	S	S.	Water st.		

SIZE	KIND (CIRCLE ONE)	PRESSURE	DEPTH OF MAIN	CONDITION OF MAIN: (CIRCLE ONE)	IF MAIN CONDITION IS POOR, WAS COUPON TAKEN?
12"	C - CAST IRON C - DUCTILE IRON <u>S - STEEL COR PRO</u> P - PLASTIC OTHER	LOW <u>MEDIUM</u> HIGH	3 FT. 5 IN.	<u>GOOD</u> POOR NOT EXPOSED	YES  NO

WORK PERFORMED: (CIRCLE ONE)	ON WHAT? (CIRCLE ONE)	REASON FOR WORK (CIRCLE ONE)								
<p style="text-align: center;"><u>JOB CODE</u></p> <p>26 - EXTERNAL SEALANT ..... (MILLER) 206</p> <p>33 - INJECTED SEALANT ..... (PERMABOND) 436</p> <p>18 - B-BOX/BASIN MAINTENANCE ..... 348</p> <p>19 - TEST HOLE ..... 248</p> <p>60 - MAIN REPLACEMENT (Kind for Kind) ..... 260</p> <p>99 - OTHER ..... 265</p> <p style="text-align: center;"><u>MANUF. CD.</u></p> <p>3 - BAND CLAMP ..... 51-DRESSER 406 53-SMITH BLAIR</p> <p><u>CORROSION WORK</u></p> <p>51 - INSTALL TEST LEAD &amp; ANODE ..... 951</p> <p>52 - INSTALL ANODE ..... <u>952</u></p> <p>54 - B-BOX MAINTENANCE ..... 954</p> <p>56 - CLEAR SHORT ..... 956</p> <p>59 - INSULATE/REINSULATE ..... 959</p> <p>67 - OTHER CORROSION WORK ..... 967</p>	<p>35 - BELL JOINT</p> <p>15 - MECHANICAL JOINT</p> <p>6 - COMPRESSION COUPLING</p> <p>13 - BROKEN MAIN</p> <p>14 - CRACK AT TAP</p> <p>31 - CORROSION HOLE IN MAIN</p> <p>20 - VALVE</p> <p>9 - DRIP/SYPHON</p> <p><u>99</u> - OTHER</p>	<p>1 - LEAK</p> <p>3 - PUBLIC IMPROVEMENT</p> <p><u>4</u> - CATHODIC PROTECTION</p> <p>6 - THIRD PARTY DAMAGE</p> <p>5 - OTHER</p>								
PRESSURE TEST INFO (REQUIRED for all installed piping)										
INSTALLED PRE-TESTED PIPE: YES NO										
PRE-TESTED PIPE CONTROL NO: <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td></tr></table>										
PRESSURE TEST: YES NO    PSI: _____ MINUTES: _____										

RESTORATION SIZE	OPENING DESCRIPTION
<u>6</u> FT. X <u>5</u> FT.	<input type="checkbox"/> STREET <input type="checkbox"/> ALLEY <input type="checkbox"/> PKWY <input checked="" type="checkbox"/> WALK <input type="checkbox"/> INS-LL <input type="checkbox"/> ASPH <input type="checkbox"/> LAWN <input checked="" type="checkbox"/> CONC <input type="checkbox"/> DIRT
_____ FT. X _____ FT.	<input type="checkbox"/> STREET <input type="checkbox"/> ALLEY <input type="checkbox"/> PKWY <input type="checkbox"/> WALK <input type="checkbox"/> INS-LL <input type="checkbox"/> ASPH <input type="checkbox"/> LAWN <input type="checkbox"/> CONC <input type="checkbox"/> DIRT

DESCRIPTION OF WORK OR REMARKS

---



---



---



---



---

CREW REPORT		
PREPARED BY	EMPLOYEE NUMBER	DATE
<u>J. Burton</u>	<u>Intran</u>	<u>7-28-2010</u>

Facility [dropdown]  
 Address (PGL) [dropdown]  
 10 n columbus [input] Go [button]

Address Location  
 Address Range  
 00 - 249 N COLUMBUS DR

