

## MONTROSE – CONSTRUCTION VISIT REPORT

**NAME:** YARISSA A MARTÍNEZ-LEÓN

**DATE/TIME:** July 1, 2013 / 3:29pm until 3:45pm

**WEATHER/WIND CONDITIONS:** light breeze

Max Temp 86.9 °F

Min Temp 65.8°F

**Work Area Location:**

Javelin St and S New Hampshire Blvd

**Work Being Performed:**

Please note that the workers were done for the day when I arrived.

However, it was visible in Javelin St and S New Hampshire Blvd that the concrete had been cut to be remove in the pedestrian walkway; and the perimeter of the asphalt was cut for the trench areas on Javelin St.

**General Observations: (General Housekeeping, Progress, Health & Safety Procedures)**

Javelin St and S New Hampshire Blvd:

-Traffic signs were placed and all the areas were secured

**Measurement System**

**VOC**

There was no excavation done on this day

**Dust**

No exceedence according to daily forms

**Noise**

No exceedence according to daily forms

**Communications:**