



Guam Waterworks Authority (VP0989)
SDWA Sanitary Survey



Tumon, Guam
Ugum Water Treatment Plant Intake Area
NEIC Field Investigation Photographs
April 25, 2012

Overview Map



File Name: RIMG0001.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/25/2012 10:04:36 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Upstream from intake along Ugum River

File Name: RIMG0002.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/25/2012 10:07:48 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	At intake showing bamboo blocking algae facing downstream toward dam

File Name: RIMG0003.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/25/2012 10:10:32 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of intake with screen

File Name: RIMG0004.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/25/2012 10:17:29 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Hole where old bridge footing was removed, downstream of intake along dam

File Name: RIMG0005.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:19:03 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Facing downstream along dam toward plunge pool

File Name: RIMG0006.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:20:30 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Facing upstream along Ugum River toward dam and intake

File Name: RIMG0007.JPG



Attributes


Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████████
Date Time Stamp	4/25/2012 10:27:21 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Three pumps, two on right in operation (pumps # 1 and # 2) and one on left is out of service (pump # 3)

File Name: RIMG0008.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:28:19 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of pump # 1 with imbalance



Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:35:26 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Pre-filter information

File Name: RIMG0010.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	4/25/2012 10:36:55 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Pre-filters

File Name: RIMG0011.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:40:50 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Turbidimeter on pre-filters

File Name: RIMG0012.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:41:01 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of reading on turbidimeter on pre-filters

File Name: RIMG0013.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:41:47 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Flow meter on pre-filters

File Name: RIMG0014.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:45:24 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Back-up generator in control building

File Name: RIMG0015.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/25/2012 10:45:34 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Control panel in control building

File Name: RIMG0016.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:45:49 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Outside control building

File Name: RIMG0017.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	████
Date Time Stamp	4/25/2012 10:51:11 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Diesel fuel tank for generator

File Name: RIMG0018.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	4/25/2012 10:52:51 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Downhill facing diesel fuel tank with Ugum River in background